



International Safety Products

Sheet 1 of 2 sheets

SERVICE BULLETIN

Service and Maintenance manual N° ALL

Bulletin N° 010/Nov/11

Equipment affected:

All ISP manufactured products including Lifejackets and Bladder Assemblies fitted with the **United Moulders (UML) Mk5 or Mk5i Automatic Inflator Cartridge**, but specifically **only** when used with the **white coloured UML "manual only over-ride" sealing cap**.

Reason for issue:

Notification of a Safety Alert issued by the Manufacturer of **United Moulders Inflators**.

Materiel required:

N/A

This bulletin is effective:

From: Immediate
To: Until Further Notice

Instruction:

Please can you review (and circulate as deemed appropriate to all service personnel / end users of products) and take appropriate actions as described in the Safety Alert issued by **United Moulders Ltd** (appended on page 2 of this bulletin).

Authorised by Name (print) : Paul Houghton

Signature : 

Position : Technical Manager

Date : 3rd November 2011

All queries relating to this Service bulletin should be addressed to: Technical Dept,
International Safety Products L^{td} Orrell mount, 159 Hawthorne Road, Bootle, Merseyside. L20 6JU. U.K.

Telephone: +44 (0)151 922 2202

Facsimile: +44 (0)151 922 5874



Safety Alert ! **UML Sealing Cap**

The UML MK5 Sealing cap is used to convert the UML Automatic Inflator range to Manual Inflation only for special purposes.

The white sealing cap in some instances will not correctly seal the black or grey MK5 or MK5i Cartridges, which may result in automatic activation on contact with water, even with the sealing cap fitted.



This only effects white sealing caps fitted on the 'black or grey MK5 & MK5i Cartridges'.



UML recommend that you immediately check your life jacket . If a white sealing cap is fitted please contact your lifejacket supplier for a replacement cap. The replacement cap will be grey in colour.

MK5
Automatic Inflator



Pro Sensor
Automatic Inflator



Black
MK5 Automatic
Cartridge

White
Sealing
Cap